

# Entry Permit Holder Report

SafeWork SA

Application ID 21433746

Entry Permit Holder	
<b>Full Name:</b>	Cody Hastings
<b>Permit Number:</b>	ET 25 00877
<b>Union Represented:</b>	CFMEU C & G Division
Worksite Entered	
<b>Business Name:</b>	Treno Projects / Build Society
<b>Industry:</b>	Construction
<b>Address:</b>	4-10 Railway Terrace, Mile End
<b>Date workplace entered:</b>	6/5/25

## I Cody Hastings am of the opinion that the PCBU has contravened the WHS legislation relating to:

	Alleged Contravention	More information	Was the contravention rectified?
PCBU Alleged Contravention 1	Not maintaining a safe work environment	<p>On a visit on the 5/5/25, site found to not have an effective emergency management plan. Safework was notified, and attended, and placed a prohibition notice on the job.</p> <p>While checking on job today, I noted that high risk works were underway (scaffold work), and suspected PCBU had not complied with the prohibition notice.</p>	No

		<p>After speaking with Safework inspector [REDACTED] prior to entry, it had not been confirmed to me that the prohibition notice had been lifted.</p> <p>While undertaking the section 117 visit today, I noted that while hand held radios and air horns had been purchased and placed outside of the stairwell along with maps of the site, there was still no emergency lighting or 'running man' signs in place. There was also no information re the emergency call channel for the radios, and the air horns were still in their original packaging (stapled shut). There had been no trial of an emergency drill, so one could not tell whether the emergency management plan was effective.</p>	
PCBU Alleged Contravention 2	Not maintaining safe plant and structures	<p>On 5/5/25 Safework attended job and placed prohibition notice on scaffold.</p> <p>Today I noted that scaffold was still being used to exit ali-mak and access working levels. Areas of edge protection/scaffold around ali-mak had not been made compliant/safe prior to other workers accessing the areas/scaffold.</p> <p>Scaffold had not had prohibition notices placed on scaffold (both external wrap, and internal atriums). Access to scaffold had not been blocked off or restricted.</p>	No
PCBU Alleged Contravention 3	Other	<p>Upon entering the job, no prohibition notices had been displayed, as per the WHS Act. Builder had started to remedy this and to display them after I raised it as a breach</p>	No
PCBU Alleged Contravention 4	Not maintaining a safe work environment	<p>Job site still had large amounts of silica throughout. While minor attempts to rectify had been made, no meaningful extra resources had been provided to address the issue.</p>	No