

Entry Permit Holder Report

SafeWork SA

Application ID 23008638

Entry Permit Holder	
Full Name:	Cody Hastings
Permit Number:	ET2500877
Union Represented:	CFMEU Construction Division
Worksite Entered	
Business Name:	St Aloysius College - Schiavello
Industry:	Construction
Address:	Angas St, Adelaide
Date workplace entered:	12/02/2026

I Cody Hastings am of the opinion that the PCBU has contravened the WHS legislation relating to:

	Suspected Contravention	More information	Was the contravention rectified?
PCBU Alleged Contravention 1	Inadequate facilities or access to facilities	Site had considerable amount of mould present in the lunchroom. A connecting back room was opened up as an alternative lunchroom, however workers trying to remove the mould contaminated carpet were travelling back and forth between the rooms, potentially bringing airborne contaminants into the 'new' lunchroom. The workers had not been provided adequate PPE, and no proper air ventilation had been set up.	No

		<p>After raising concerns with the builder, they closed the 'new' lunchroom due to concerns about bringing contaminants into the room.</p> <p>The site shut access to the 'new' lunchroom for several days, and has since re-opened the lunchroom claiming that it was now safe, however no documentation, or hygienists report has been provided to the CFMEU, or to workers, despite requesting this happen several times.</p>	
PCBU Alleged Contravention 2	Inadequate facilities or access to facilities	The site had no female toilets on-site, despite there being several female workers.	No
PCBU Alleged Contravention 3	Not maintaining a safe work environment	Site had an unacceptable build up of silica dust throughout the job.	No
PCBU Alleged Contravention 4	Not maintaining a safe work environment	<p>Site had no emergency running man lights throughout site.</p> <p>Site had inadequate emergency access lighting.</p> <p>Some emergency access lighting did not have battery back up capabilities.</p>	No
PCBU Alleged Contravention 5	Not maintaining a safe work environment	Site has a large amount of non compliant edge protection due to there being a gap greater than 10mm below the kickers and screens.	No
PCBU Alleged Contravention 6	Not maintaining a safe work environment	<p>Site had several power leads running along the ground creating trip hazards.</p> <p>Bubblers had waste water exiting over the top of power points.</p>	No