

Entry Permit Holder Report

SafeWork SA

Application ID 21453497

Entry Permit Holder	
Full Name:	Cody Hastings
Permit Number:	ET 25 00877
Union Represented:	CFMEU C & G Division
Worksite Entered	
Business Name:	Treno Projects / Build Society
Industry:	Construction
Address:	4-10 Railway Terrace, Mile End
Date workplace entered:	9/5/25

I Cody Hastings am of the opinion that the PCBU has contravened the WHS legislation relating to:

	Alleged Contravention	More information	Was the contravention rectified?
PCBU Alleged Contravention 1	Not maintaining a safe work environment	Builder has failed to display the following prohibition notices and provisional improvement notices on the job: WHSIN 275517 - Housekeeping WHSPN 275486 - Access and egress WHSPN 275487 - Risk of falls (L6 Roof) WHSIN 275509 - Lighting WHSIN 275513 - First Aid WHSIN 275515 - Fire Extinguishers	No

		Where builder had displayed prohibition notices, reasonable steps had not been taken to ensure the notices would not be damaged by the weather/environment (ie no lamination, or plastic sleeves).	
PCBU Alleged Contravention 2	Not maintaining a safe work environment	<p>Builder has failed to restrict access to L7 and L6 roof, as well as failing to restrict access to external scaffold from working levels.</p> <p>Scafftag was still located on the external scaffold in a position which does not indicate it could not be used.</p> <p>Builder had only used flagging to restrict access to stretcher stair from the ground, as opposed to a hard barrier.</p>	No
PCBU Alleged Contravention 3	Not maintaining safe plant and structures	<p>Since prohibition notices were placed on the job on Monday 5/5/25, works have clearly taken place on the atrium scaffold (which since Monday has been under a prohibition notice) that is not related to rectification works (approx. 3m lift).</p> <p>Photographic evidence can be provided.</p>	No
PCBU Alleged Contravention 4	Not maintaining safe plant and structures	No stretcher could be found onsite, and was not located in the site office as per the sites emergency management plan	No
PCBU Alleged Contravention 5	Not maintaining a safe work environment	<p>Multiple airhorns on site were either smashed or missing, meaning the site is not maintaining its emergency management plan.</p> <p>Evacuation maps on site do not meet the Australian standards (AS 3745).</p> <p>On some levels the emergency call plan was not displayed, or was not positioned near the emergency radios (ie channel #).</p> <p>Builder could not provide registrar/details of their practise evacuation drill except for photos of a gathering of people.</p>	No

		No muster location signs were displayed in the supposed muster location.	
PCBU Alleged Contravention 6	Not maintaining a safe work environment	<p>While attempting to fix the access issues on level 7, builder had created a cut risk by failing to remove or cover sharp edges of cut partition wall stud frame (as opposed to just removing whole frame).</p> <p>Workers were also exposed to cut risk from scaffold tubing used on atrium due to cut ends not being blunted.</p>	No
PCBU Alleged Contravention 7	Not maintaining a safe work environment	<p>There was access/egress issues on some levels due to bin, material, and waste build up, restricting the ability to get a stretcher through in case of emergency.</p> <p>Scaffold tube off of atrium was also impeding the accessways, restricting the ability to get a stretcher through in case of emergency.</p>	No
PCBU Alleged Contravention 8	Not maintaining a safe work environment	<p>Areas of L3 and Ground had non-compliant edge protection, exposing workers underneath to the risk of dropped objects.</p> <p>Edge protection between ali-mak and working levels had non compliance (no kickers), exposing persons underneath to a risk of dropped objects.</p>	No
PCBU Alleged Contravention 9	Not maintaining safe plant and structures	Part of the flooring on one of the prestons was loose, and lifting, exposing workers to a trip hazard.	No
PCBU Alleged Contravention 10	Not maintaining a safe work environment	<p>Site still had very poor housekeeping. There was still a build up of silica on the internal stairwell as well as throughout multiple levels.</p> <p>There was also still a build up of waste through multiple areas where trades had been working.</p>	No