

# Entry Permit Holder Report

SafeWork SA

Application ID 21579250

Entry Permit Holder	
<b>Full Name:</b>	Peter Russell
<b>Permit Number:</b>	ET-25-1913
<b>Union Represented:</b>	United Firefighters Union of South Australia Inc
Worksite Entered	
<b>Business Name:</b>	Kadina Fire Station
<b>Industry:</b>	Other Firefighting
<b>Address:</b>	13 Ewing Street Kadina
<b>Date workplace entered:</b>	2-6-2025

## I Peter Russell am of the opinion that the PCBU has contravened the WHS legislation relating to:

	Alleged Contravention	More information	Was the contravention rectified?
PCBU Alleged Contravention 1	Inadequate facilities or access to facilities	Regulation 41  Plumbing issues relating to drainage have rendered the shower unusable, and the bathroom is being used for storing materials, including a firefighters locker.  The significance of washing facilities is escalated by the nature of work being performed at the workplace. Firefighters who return from Fire Fighting incidents are unable to decontaminate at the station. This	No

		necessarily requires Firefighters to take contamination home with them.	
PCBU Alleged Contravention 2	Inadequate facilities or access to facilities	The tiles in the bathroom are broken, and the permit holder was advised by workers that firefighters have previously suffered cuts as a result.	No
PCBU Alleged Contravention 3	Inadequate facilities or access to facilities	A temporary showering facility stored behind the station that was provided is unusable, has never been attached to running water or plumbed, and is unusable (and no gate was provided to lead to this facility).	No
PCBU Alleged Contravention 4	Inadequate facilities or access to facilities	The hot and cold-water taps are dangerously reversed (i.e. the hot tap appears on the right, the cold tap on the left), creating a risk of scalding.	No
PCBU Alleged Contravention 5	Inadequate facilities or access to facilities	The hand towel dispenser is visibly rusted.	No
PCBU Alleged Contravention 6	Inadequate facilities or access to facilities	The plumbing difficulties causes damage to the concrete at the rear of the building creating an unsafe walking surface	No