

# Entry Permit Holder Report

SafeWork SA

Application ID 21791450

Entry Permit Holder	
<b>Full Name:</b>	Cody Hastings
<b>Permit Number:</b>	ET 2500877
<b>Union Represented:</b>	CFMEU (C&G Division)
Worksite Entered	
<b>Business Name:</b>	The Dome (Hallett Group Green Cement Factory)
<b>Industry:</b>	Construction
<b>Address:</b>	Ocean Steamers Road, Port Adelaide
<b>Date workplace entered:</b>	14/07/2025

## I Cody Hastings am of the opinion that the PCBU has contravened the WHS legislation relating to:

	<b>Alleged Contravention</b>	<b>More information</b>	<b>Was the contravention rectified?</b>
PCBU Alleged Contravention 1	Inadequate facilities or access to facilities	Worksite had lunchroom amenities/space for approx. 20 workers, while there were over 40 workers onsite. This has previously been raised with the builder, with the explanation that while lunch breaks may be staggered, it does not address the issue if everyone has to sit in the lunch sheds while it rains (due to no covered walkways being provided).	No

		Currently the site is reliant on outside seating, which has no protection from the elements.	
PCBU Alleged Contravention 2	Inadequate facilities or access to facilities	Worksite has made no ruling on a set smokers area, resulting in people smoking at the outside tables, which is still in the lunchroom area, meaning non-smokers are inhaling secondary smoke.	No
PCBU Alleged Contravention 3	Not maintaining a safe work environment	Areas of the job, especially in the upper areas where form work is taking place, is exceptionally congested, with trades working, at times literally, over the top of each other. This is exacerbated by materials congesting walkways/secondary points of access at some areas of the job.	No
PCBU Alleged Contravention 4	Lack of information, training, instruction or supervision	Worksite recently had an air monitoring report done, in which the report noted workers had been dry sweeping, and recommended that HEPA filter vacuums be used. This has been raised on previous visits by the Union. While on site a worker was witnessed dry sweeping. Believe the site needs to do more to support and educate workers in the handling of silica, as we are not aware of any workers being provided with silica awareness training.	No