

Entry Permit Holder Report

SafeWork SA

Application ID 23796917

Entry Permit Holder	
Full Name:	Troy McIntyre
Permit Number:	ET2404448
Union Represented:	CFMEU - Construction Division
Worksite Entered	
Business Name:	Waterloo Corner Pre-cast Facility
Industry:	Construction
Address:	32 Dunn Rd, Waterloo Corner, SA , 5110
Date workplace entered:	09/07/2026

I Troy McIntyre am of the opinion that the PCBU has contravened the WHS legislation relating to:

	Suspected Contravention	More information	Was the contravention rectified?
PCBU Alleged Contravention 1	Inadequate monitoring of the health of workers and the conditions at the workplace	Upon entering site, I asked the PCBU if air monitoring had been conducted, which it had, and I have obtained a copy of the report. After enquiring about static air monitoring, I was told there were some around, but nobody could tell me the locations. I observed the automated cleaning robot begin its cleaning process with the roller door still up. This is supposed to be an encapsulated area because of the nature of the processes involved in there including the sanding of cured	No

		panels and the abrasing of moulds. I was told by the PCBU this was not supposed to happen but could be rectified by a re-programming or re-calibration of the system. By the failure of this control measure, I would say the PCBU has failed to provide adequate air monitoring for this area and possible exposure of RCS. This being what I would consider a high risk area because of the aforementioned processes, I would expect the PCBU in its due diligence would put a static air monitor in this location.	
PCBU Alleged Contravention 2	Not maintaining safe systems of work	Regulation 35,36 and 38. The PCBU not having appropriate control measures in place for when the workers are cleaning and preparing the moulds. I observed the use of a scraper to clean dried concrete off the mould and drilling concrete out of the holes for the plastic lugs to go into. No water for dust suppression or any PPE being worn. I was also told by the workers they are dry sweeping because they are not supplied with water sprayers. When I raised the issue of dust suppression to the PCBU in relation to the moulds. I was told it would be a problem because of the electrical connections controlling the hydraulics.	No