

# Entry Permit Holder Report

SafeWork SA

Application ID 21228314

Entry Permit Holder	
<b>Full Name:</b>	Chelsea Bishop
<b>Permit Number:</b>	ET-23-02248
<b>Union Represented:</b>	SDA
Worksite Entered	
<b>Business Name:</b>	The Reject Shop Gilles Plains
<b>Industry:</b>	Retail Trade
<b>Address:</b>	575 North East Road, Gilles Plains SA 5086
<b>Date workplace entered:</b>	26/03/2025

**I Chelsea Bishop am of the opinion that the PCBU has contravened the WHS legislation relating to:**

	<b>Alleged Contravention</b>	<b>More information</b>	<b>Was the contravention rectified?</b>
PCBU Alleged Contravention 1	Not maintaining a safe work environment	Workers reported heat stress and mould concerns. Heat stress concerns in back dock (26.8C) and back half of shop floor (26.4C). Both areas lack ventilation and airflow. Work required in these areas is physical with stock management. Workers report when working in these areas they have experienced excessive sweating, fatigue and nausea. Workers also reported increase of customer complaints. TRS provided a pedestal fan approx. 1 month ago for the back	No



		<p>area, but this is only effective when standing directly in front of it. PCBU aware of concerns and workers report there has been a lack of communication on action taken. Unable to confirm if mould present, but the store ceiling is visibly water damaged. Workers reported that when there is heavy rain, the ceiling pools with water, specifically in the back area. Ceiling tiles throughout the store are loose. Workers report PCBU are aware of the issue. Concerns with the stability of the ceiling; site was closed mid 2024 due to ceiling collapse</p>	
--	--	--	--

