

Entry Permit Holder Report

SafeWork SA

Application ID 23177767

Entry Permit Holder	
Full Name:	Cody Hastings
Permit Number:	ET2500877
Union Represented:	CFMEU Construction Division
Worksite Entered	
Business Name:	Hallett Dome
Industry:	Construction
Address:	Ocean Steamers Rd, Port Adelaide
Date workplace entered:	20/03/2026

I Cody Hastings am of the opinion that the PCBU has contravened the WHS legislation relating to:

	Suspected Contravention	More information	Was the contravention rectified?
PCBU Alleged Contravention 1	Not maintaining a safe work environment	Site had an incident where workers reported being able to smell ammonia while undertaking commissioning work. Workers removed themselves from the area, and commissioning works have since been ceased. The cause of ammonia smell is believe to have come from the 'flyash', and the fact the silo the fly ash was in did not have a chemicaland gas extraction, only dust extraction, where the extraction output was in the work area, resulting in the extraction fans pulling	No

		<p>the chemical and gas in to the work area.</p> <p>Since the incident the site team have purchased a single, wearable, ammonia detector, and have maintained a cease work on commissioning works.</p> <p>Union advised site team to ensure all workers in area were provided with a wearable ammonia detector, but also to install a full spectrum, perm. air quality testing system, as the site couldnt confirm whether any other chemicals and gases had been released during the commissioning process, and so that results can be shared with workers regularly.</p>	
PCBU Alleged Contravention 2	Not maintaining a safe work environment	<p>Union also advised site to amend the extraction system so that the extraction system terminated outside and not in an enclosed work area.</p> <p>Site team explained they intended to extend the extraction system to it terminated in the driveway, however this would still be in an inside and undercover area, advised this should terminate outside.</p>	No
PCBU Alleged Contravention 3	Inadequate monitoring of the health of workers and the conditions at the workplace	<p>Site had not provided exposed workers with the ability to be sent for health checks to ensure there were not long term negative side effects. Since EPH visit, site said they will try to arrange something.</p> <p>Site does not have any air monitoring set up at the output of the extraction system to detect for chemicals and gases.</p>	No
PCBU Alleged Contravention 4	Not maintaining a safe work environment	<p>Inside of the dome had poor housekeeping as there was a build of dust throughout.</p>	No