

# Entry Permit Holder Report

SafeWork SA

Application ID 22262511

Entry Permit Holder	
<b>Full Name:</b>	Tasha Lee Linke
<b>Permit Number:</b>	ET-23-03616
<b>Union Represented:</b>	United Workers Union
Worksite Entered	
<b>Business Name:</b>	Vinarchy Wines - Rowland Flat Winery
<b>Industry:</b>	Manufacturing
<b>Address:</b>	1914 Barossa Valley Way, Rowland Flat South Australia 5352
<b>Date workplace entered:</b>	26/09/2025

**I Tasha Lee Linke am of the opinion that the PCBU has contravened the WHS legislation relating to:**

	<b>Suspected Contravention</b>	<b>More information</b>	<b>Was the contravention rectified?</b>
PCBU Alleged Contravention 1	Not maintaining a safe work environment	As walking towards Warehouse 2 there are a number of roller doors that are used to gain access in and out of the warehouse area. Only one door has colour coded lights to indicate if the door is being approached from the inside of the warehouse despite all doors being used frequently. No signage present to explain what the colour coding is, PCBU was unsure of the colour coding system when questioned.	No

PCBU Alleged Contravention 2	Inadequate facilities or access to facilities	<p>No hand sink in Warehouse 2 meaning that workers have been instructed to use the emergency shower and eye wash station to wash their hands.</p> <p>There is a sink on site ready for installation, however it is sitting in a box and the PCBU was not able to give a definitive answer on when installation would occur.</p>	No
PCBU Alleged Contravention 3	Not maintaining safe systems of work	Intercom in Warehouse 2 not working correctly and is inaudible meaning workers would not hear the instructions to evacuate work area in case of emergency.	Yes
PCBU Alleged Contravention 4	Not maintaining a safe work environment	<p>Eyewash station being used to wash hands due to no handwashing station in Warehouse 2 area.</p> <p>Chemicals can be used within this area, some of which are incredibly dangerous if you get them in your eyes. If a worker was to use the eyewash station, there is no guarantee they would not be further exposed to chemicals if someone has washed chemicals off their hands in this station.</p> <p>Emergency shower and eye wash station is not plumbed in sufficiently and has no drainage around it, meaning that when used it creates further hazard of slipping or falling.</p>	No
PCBU Alleged Contravention 5	Not maintaining a safe work environment	<p>Floors within Warehouse 2.</p> <p>Warehouse 2 has been repurposed into a wine production and storage area which often results in the floors getting wet. The floors are of a glossy coating which has been resulting in multiple near misses or people slipping and falling daily.</p> <p>No slip mats in place.</p> <p>Forklifts operating in this area can sometimes lose traction and spin their wheels if traveling over a wet area.</p> <p>PCBU was not able to give a definitive answer of when the gripping would go down on the floors.</p>	No

PCBU Alleged Contravention 6	Not maintaining a safe work environment	<p>No bubble mirrors hanging at the end of rows within Warehouse 2 area making it hard for the forklift drivers to see what is in their travel path.</p> <p>PCBU stated that mirrors would be taken from other area's and installed in upcoming weeks.</p>	No
PCBU Alleged Contravention 7	Not maintaining a safe work environment	Drygoods Warehouse floor is cracked and falling apart making it hard for the reach truck to travel across certain area's resulting in repetitive bouncing and pressure on employee's backs as a result of the reach truck having to go over uneven surfaces.	No